



# Material Safety Data Sheet

NFPA	HCS Risk Phrases	Protective Clothing
	HCS Class: Irritating substance	Splash goggles Respirator Gloves

## Section I. Chemical Product and Company Identification

Common Name/ Trade Name	<b>SUPER SLUMP BUSTER</b>	Last Update	03/01/2014
Supplier/ Manufacturer:	FRITZ-PAK CORPORATION 4821 Eastover Circle Mesquite, TX, 75149, U. S. A. Tel: 214-221-9494 Fax: 214-349-3182		

## Section II. Composition and Information on Ingredients:

Name	CAS #	LC <sub>50</sub> /LD <sub>50</sub>
Soda Ash	497-19-8	Oral (LD50) mg/kg: Acute: 5140 (Rat). Dermal (LD50) mg/kg: Acute: 4000 (Rabbit).

## Section III. Hazards Identification

Potential Acute Health and Chronic Effects	Slightly dangerous in case of skin contact (irritant), of eye contact (irritant), of ingestion, of inhalation. Corrosive to eyes and skin.
--	--

## Section IV. First Aid Measures

Eye Contact	Check for and remove any contact lenses. IMMEDIATELY flush eyes with running water for at least 15 minutes, keeping eyelids open. COLD water may be used. DO NOT use an eye ointment. Seek medical attention.
Skin Contact	Remove contaminated clothes and place the victim under a shower. Wash the contaminated skin with running water and non-abrasive soap.
Inhalation	Allow the victim to rest in a well ventilated area. Seek immediate medical attention.
Ingestion	DO NOT induce vomiting. Have conscious person drink several glasses of water or milk. Seek immediate medical attention.

## Section V. Fire and Explosion Data - Non-Flammable

## Section VI. Accidental Release Measures

Small Spill	Place the spilled solid in a convenient waste disposal container.
Large Spill	

## Section VII. Handling and Storage

Precautions	Keep container dry. Keep away from heat. Keep away from sources of ignition. In case of insufficient ventilation, wear suitable respiratory equipment. Avoid contact with skin and eyes. Keep away from incompatibles as acids.
Storage	Keep material dry. Keep in a cool place.

## Section VIII. Exposure Controls/Personal Protection

Engineering Controls	Use process enclosures, local exhaust ventilation, or other engineering controls to keep airborne levels below recommended exposure limits.
Personal Protection	Splash goggles. Wear appropriate respirator when ventilation is inadequate.

Continued on Next Page

**Section IX. Physical and Chemical Properties**

**Section X. Stability and Reactivity Data**

**Stability** The product is stable.

**Incompatibility with various substances** Reactive with acids.

**Corrosivity** Slightly corrosive to corrosive in presence of aluminum.

**Section XI. Toxicological Information**

**Section XII. Ecological Information - Not Available**

**Section XIII. Disposal Considerations**

**Waste Disposal** Recycle to process if possible. Consult your local or regional authorities.

**Section XIV. Transport Information - Not Regulated**

**Section XV. Other Regulatory Information and Pictograms**

**Federal and State Regulations** Not available

**Other Classifications** **WHMIS (Canada)** WHMIS CLASS E:

<b>Health Hazard</b>	<b>2</b>
<b>Fire Hazard</b>	<b>0</b>
<b>Reactivity</b>	<b>0</b>



*The information contained herein is based on data considered accurate. However, no warranty is expressed or implied regarding the accuracy of these data or the results to be obtained from the use thereof. Fritz-Pak Corporation assumes no responsibility for personal injury or property damage to vendees, users or third parties caused by the material. Such vendees or users assume all risks associated with the use of the material.*